



Unannounced

915/1000

**Sumol + Compal Marcas, S.A. - 2299
Pombal, Leiria, Portugal**

was inspected by a qualified AIB International inspector on

October 17, 2023 - October 19, 2023

under the requirements of the AIB International
Consolidated Standards for Beverage Facilities

Scope: 8 filling lines - 42,000 sq meters covered

A handwritten signature in black ink, appearing to read 'Daniel R. Martin'.

PRESIDENT AND CEO

The inspection is based on observations on the date of inspection. AIB International recommends periodic inspections on at least an annual basis.